

# Using LINMON on a VMS System

---

1. At the online VMS host prompt, type:

```
Tools <Enter>
```

2. Next, type:

```
linmon <enter>
Enter NCC id, or Q for Quit [Default = 1]:2
Enter R (Monitor RTU), L (Monitor Line), or Q for Quit:
[Default = R]
Enter RTU id, or Q for Quit [Default = 1]:12
Enter H (HEX) or A (ASCII): [Default = H]
Enter file name or C/R for only the terminal:
4300060297C1 00430603B2514 300060417C3 004306053253
```

3. To quit the program, type:

```
<enter>
q <enter>
```