

End of Life Notice

Product	EOL Date	Replacement
6000-1140 Low Power Logic Processor	February 1, 2018	NO REPLACEMENT
6000-1150 Logic Processor	February 1, 2018	NO REPLACEMENT
8600-2504 — 2500 Series Logic Processor	October 31, 2019	8600-3343F
1362 — CI Pulse Input Adapter	October 31, 2019	NO REPLACEMENT
1014 — Fiber Optic Modem	October 31, 2019	NO REPLACEMENT
1354 — 1200 Baud Asynchronous Modem	October 31, 2019	TBD
2523 — Dual Processor Failover Board	October 31, 2019	NO REPLACEMENT
HSQ-DAT72 — Tape Drive	October 31, 2019	NO REPLACEMENT
HSQ-GC2 — Dual Video Card	October 31, 2019	NO REPLACEMENT
HSQ-GC4 — Quad Port Video Card	October 31, 2019	NO REPLACEMENT
HSQ-ETH2 — Dual Port Ethernet Card	October 31, 2019	NO REPLACEMENT
2516-182 — 150 Watt Power Supply	October 31, 2019	CP10.241-S1
2516-183 — 100 Watt Power Supply	October 31, 2019	CP10.241-S1
2506 — 16 Ch. DI / 16 Ch. DO	October 31, 2019	2569 – 16 Ch. DI / 16 Ch. DO
Exceed14	October 31, 2019	Exceed15
RTU-DELV — Development Software for 2504	October 31, 2019	NO REPLACEMENT
HSQ-TALK3 — MISERTalk Hardware	October 31, 2019	HSQ-TALK and HSQ-PAGE
HSQ-DIALIN	May 31, 2020	NO REPLACEMENT
8600-3343Z2 — Extended Temperature Logic Processor	May 31, 2020	NO REPLACEMENT
2505 Power Control Board	August 1, 2020	2585
2510 — 64-Channel DO Board	August 1, 2020	HSQ-6200 Series Modules
2587 — 64-Channel TTL DI Board	December 31, 2020	HSQ-6200 Series Modules
EP-BURN — EPROM Burner	December 31, 2020	NO REPLACEMENT
RTS-GEN — RTS Generator	December 31, 2020	NO REPLACEMENT
HSQ-6024	January 2, 2021	HSQ-6200 Series Modules

NOTE: Once a product has reached its End-of-Life it will no longer be available for purchase as new. However, repairs of existing equipment may be possible if the necessary parts are obtainable. Please contact repairs@hsq.com or [Chris Cornejo](#) at (510) 259-3707 to check availability.

Repairs will only be accepted with an HSQ-issued RMA.